

Summary Information on Underground Storage Tanks (USTs)

(Apr 27, 2009)

This is summary information. If you wish to get data on individual facilities, please see our [other reports](#).

General Information

Total Number of UST Facilities: 1212
Total Number of USTs: 3370

Summary Information for On-Site Inspections

Number of UST Facilities Inspected: 246
Inspection Period Dates: Jun 3, 2008 To: Apr 27, 2009
Percent in Total Compliance: 48%
Note: Tank, facility, and on-site inspection compliance information is based on 58.01.07 and 40 CFR 280 (adopted by reference) rules. On-site inspections measure compliance with every provision of these rules.

Summary Information for Releases

Number of Confirmed UST Releases: 1405
Release Reporting Period Dates: Jun 19, 1982 To: Apr 27, 2009

Summary Information for Release Sources and Causes

The data below is information on releases that have reported source and/or cause data.

Source			Cause																							
			Equipment Failure		Corrosion		Elongated Piping		Microbial Piping Growth		Loose Dispenser Fittings		OverFill		Unknown		Spill		Installation Problem		Manufacturer defect		Construction Activities			
	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#		
Tank	37.50	18	2.08	1	14.58	7									10.42	5										
Piping	22.92	11	10.42	5											6.25	3			2.08	1						
Metal Flex Connector	2.08	1													2.08	1										
Dispenser	8.33	4	4.17	2							2.08	1														
Spill Bucket	0.00	0																								
Fill Pipe	0.00	0																								
Unknown	16.67	8													14.58	7										
STP Area	2.08	1	2.08	1																						
Piping Joints	6.25	3	2.08	1											2.08	1			2.08	1						
Tank Joints	0.00	0																								
Vent Line	0.00	0																								
Delivery Hose	2.08	1															2.08	1								
Other	2.08	1											2.08	1												

= number, %= percent of total number of confirmed releases

Note: Release, source, and cause information is based on confirmed releases of all regulated facilities since September 1, 2007.
Source and cause data were collected using DEQ personnel information, insurance information, owner and/or operator information, and/or consultant information.